


INTERACTIVE MICROWARE, INC.

Copyright (c) 1980




By Paul K. Warne


## CURVE FITTER

CURVE FITTER  
CURVE FITTER

Interactive Microware, Inc.  
P.O. Box 771  
State College, Pa 16801  
(814) 238-8294



SINGLETOM



12 FEATURES OF CURVE FILTER  
 13 HOW TO PRODUCE A BACKUP DISK  
 14 METHODS OF USER INTERACTION  
 15 HOW TO RUN THE DEMONSTRATIONS  
 16 CONTROL CHARACTERS FOR EDITING AND PROGRAM CONTROL  
 17 USING THE FLOWCHARTS  
 18 READ FORMAT FILE NAME  
 19 INPUT STANDARDS (FLOWCHART B)  
 20 X,Y PAIRS (Y:N)  
 21 FIRST X VALUE  
 22 X INTERVAL  
 23 ERROR BARS (Y:N)  
 24 DISK, KEYBOARD OR SENSOR INPUT  
 25 READ FILE NAME  
 26 FIRST POINT TO BE USED  
 27 INTERVAL BETWEEN POINTS  
 28 X VALUE, Y VALUE, +/- ERROR  
 29 SCALE STANDARDS (FLOWCHART C)  
 30 INTERCHANGE X & Y DATA (Y:N)  
 31 X SCALE FACTOR  
 32 X LOG SCALE  
 33 Y SCALE FACTOR  
 34 Y LOG SCALE  
 35 Y OFFSET  
 36 X OFFSET  
 37 Y LOG SCALE  
 38 X LOG SCALE  
 39 Y LOG SCALE  
 40 X OFFSET  
 41 Y OFFSET  
 42 X LOG SCALE  
 43 Y LOG SCALE  
 44 X LOG SCALE  
 45 Y LOG SCALE  
 46 X LOG SCALE  
 47 Y LOG SCALE  
 48 X LOG SCALE  
 49 Y LOG SCALE  
 50 X LOG SCALE  
 51 Y LOG SCALE  
 52 X LOG SCALE  
 53 Y LOG SCALE  
 54 X LOG SCALE  
 55 Y LOG SCALE  
 56 X LOG SCALE  
 57 Y LOG SCALE  
 58 X LOG SCALE  
 59 Y LOG SCALE  
 60 X LOG SCALE  
 61 Y LOG SCALE  
 62 X LOG SCALE  
 63 Y LOG SCALE  
 64 X LOG SCALE  
 65 Y LOG SCALE  
 66 X LOG SCALE  
 67 Y LOG SCALE  
 68 X LOG SCALE  
 69 Y LOG SCALE  
 70 X LOG SCALE  
 71 Y LOG SCALE  
 72 X LOG SCALE  
 73 Y LOG SCALE  
 74 X LOG SCALE  
 75 Y LOG SCALE  
 76 X LOG SCALE  
 77 Y LOG SCALE  
 78 X LOG SCALE  
 79 Y LOG SCALE  
 80 X LOG SCALE  
 81 Y LOG SCALE  
 82 X LOG SCALE  
 83 Y LOG SCALE  
 84 X LOG SCALE  
 85 Y LOG SCALE  
 86 X LOG SCALE  
 87 Y LOG SCALE  
 88 X LOG SCALE  
 89 Y LOG SCALE  
 90 X LOG SCALE  
 91 Y LOG SCALE  
 92 X LOG SCALE  
 93 Y LOG SCALE  
 94 X LOG SCALE  
 95 Y LOG SCALE  
 96 X LOG SCALE  
 97 Y LOG SCALE  
 98 X LOG SCALE  
 99 Y LOG SCALE

INTERACTIVE MICROWARE, INC.

Copyright © 1980

By Paul K. Warne

CURVE FITTING

Interactive Microwave, Inc.  
P.O. Box 771  
State College, Pa 16801  
(814) 238-8294



CURVE FITTER UPDATE #1

SCIENTIFIC PLOTTER AND CURVE FITTER CHANGES FOR USE  
WITH SILENTYPE PRINTER

24 PLOMCHARTS

23 REFERENCES

22 LEAST SQUARES FITTING

21 INTERPOLATION

20 AVERAGING AND SMOOTHING

THEORETICAL CONSIDERATIONS OF CURVE FITTING

20 USAGE WITH SCIENTIFIC PLOTTER

19 ERASE GRAPH (Y:N)

19 WRITE FORMAT FILE NAME

19 WRITE UNKNOWN FILE NAME

19 WRITE STANDARDS FILE NAME

18 SAVE FILES (FLOMCHART H)

18 MORE UNKNOWNS (Y:N)

17 READY FOR LISTING (Y)

17 X VALUE, Y VALUE, MULTIPLE

17 MULTIPLE, TYPE 0 IF VARIABLE

17 ENTER X OR Y VALUES

16 INPUT UNKNOWN VALUES (Y:N)

EVALUATE UNKNOWNS (FLOMCHART G)

16 ERASE FITTED CURVE (Y:N)

16 STATISTICS (Y:N)

15 DEGREE OF POLYNOMIAL

15 LEAST SQUARES

14 LINEAR, GEOMETRIC, EXPONENTIAL OR POLYNOMIAL

14 DEGREE OF POLYNOMIAL

13 POLYNOMIAL, CUBIC SPLINE OR STINEMAN INTERPOLATION

13 # POINTS ON CURVE

12 INTERPOLATION OR LEAST SQUARES FITTING

12 NEXT SYMBOL

11 CURVE FITTING (FLOMCHART F)

11 # POINTS AVERAGING

11 MAKE PERMANENT (Y:N)

11 # POINTS SMOOTHING

10 LIST STANDARDS (Y:N)

LIST AND PLOT STANDARDS (FLOMCHART D)

10

DOS 3.3 format.

To convert our programs to DOS 3.3 form, boot the DOS 3.3 System Master disk, type RUN MUFFIN, and follow the instructions to copy the desired programs to a disk that has been INITIALIZED in

program is run on a DOS 3.2 system.

If the disk is labeled DOS 3.2/3.3, turn off the computer and insert our program disk and turn the computer on. The DOS 3.2 operating system is first loaded from our disk, and then the HELLO

disk and press RETURN.

You to mount the DOS 3.2 (13-sector) disk, insert our program BURN BOOTT13. Then, when the prompted message appears on the screen tells the BASICS diskette or mount the System Master disk and type

IF the disk is labeled DOS 3.2, you must boot your system with

#### DOS 3.3 USERS:

You should be able to boot, load, or copy programs from any of our disks labeled DOS 3.2 or DOS 3.2/3.3.

#### DOS 3.2 USERS:

programs are copy protected, so it is illegal to make copies, except programs are not copy protected; however, please note that the program (on your System Master disk). For your convenience, the format, as supplied, to a DOS 3.3 formatted disk by using the MUFFIN DOS 3.3 system, the programs can be converted from the DOS 3.2 DOS 3.2 or DOS 3.2/3.3 (double boot) format. If you are using the system. The label on the disk indicates whether the disk is system. All either a DOS 3.2 (13-sector) or DOS 3.3 (16-sector) disk format or in a special "double boot" format which can be booted on either a DOS 3.2 (13-sector) or DOS 3.3 (16-sector) disk

#### NOTES ON PROGRAM LOADING

Interactive Microwave Programs are supplied either in DOS 3.2 format or in a special "double boot" format which can be booted on either a DOS 3.2 (13-sector) or DOS 3.3 (16-sector) disk





The best feature of Curve Fitter is its finely-tuned user interface. Many convenient features have been built into this interface. Program from the ground up. The allowable range of input values is indicated and a warning message is printed if you mistakenly enter an improper answer. At any time, you may save the working file on disk and repeat the fitting procedure. All previous selected options automatically become the defaults, so that you can quickly step through the program up to the point where a change is required. All of the options selected during the fitting procedure may be saved on the disk as a format file, which may be used for future runs on similar data. With all of these features, you will not be surprised to learn that the

- \* Demosstration littles on disk make it easy to explore the capabilities of this system.
  - \* Data may be entered as x,y pairs or as y values at fixed x intervals.
  - \* All working files may be saved on disk, thus making it possible to repeat the run later or transfer results to other programs, such as Scientific Plotter.
  - \* The known points and fitted curves are nicely plotted using high resolution graphics (280 by 192 points).
  - \* The axes are automatically scaled and numeric labels are printed along the axes.
  - \* Four different plotting symbols may be used to distinguish multiple curves on the same graph.
  - \* A single key stroke switches between text and graphics modes, so that you can alternate between viewing the questions or the graph.
  - \* The switch from text to graphics mode back is done automatically whenever the graph is being updated, so that you can see what is going on.

Other features of curve fitted that make it especially useful are:

Curves fitted to easy for scientists to fit a wide variety of curves to their experimental data and select the curve that best fits their results. Data may be input from the keyboard, from a disk file or from a special sensor, such as a spectrophotometer or pH meter. After scaling the raw data or adding a constant offset or converting to log form, N-point averaging a smooth may be carried out to reduce noise. Then, a curve N-point smoothed between the data points, using the may be interpolated between the data points, a curve polynomial, cubic spline or Spline interpolation method.

author of this program is a scientist who understands your needs make copies for your own use on a single machine. Thus, your first action should be to copy the master disk to another disk as follows:

1. Mount the master disk and type RUN CURFIT, and then press the RETURN key (from now on, you should always press RETURN after entering your command or response). After a short time, a copy right notice will appear and then the screen will be erased and the question "READ FORMAT FILE NAME? (NONE)" will appear. Now, type control Q (hold down the CONTROL key and press the Q key) to stop the program.

2. Mount the slave disk and type SAVE CURFIT. After the program has been saved on disk, type BSAVE FITCHAR,A\$3F00,L\$P2 in order to save the machine language part of the program.

3. The demonstration plot files may be saved on your slave disk later as described below.

Before you actually use this program, there are a few things that you should know about. The program will guide you through the fitting procedure by printing a series of prompts that ask questions. Each question is followed by another clause with options. Each clause specifies the range of permission that you can use to fit a curve. These clauses are based on previous information. If you type a response outside this range, the program will ring the bell and print responses, based on previous information. If you type a response that is outside the default value, which is initially blank, but this indicates the default value, which is contained in <> brackets. Later, it will contain the default value, which is just press the RETURN key.

Default values may also be read from a file stored on disk. If you wish to accept the default value, just press the RETURN key. Otherwise, type a different response, followed by RETURN. This method of saving the last response as the default value will save you a great deal of typing. Of course, if nothing is printed within the <> brackets, no default value is available and you must type some valid response.

## METHODS OF USER INTERACTION

Although this program is copyrighted, you have permission to copy it to another computer if you like. However, you must understand that you should never use it on a single machine. Thus, your first action should be to copy the master disk to another disk as follows:

1. Mount the master disk and type RUN CURFIT, and then press the RETURN key (from now on, you should always press RETURN after entering your command or response). After a short time, a copy right notice will appear and then the screen will be erased and the question "READ FORMAT FILE NAME? (NONE)" will appear. Now, type control Q (hold down the CONTROL key and press the Q key) to stop the program.

2. Mount the slave disk and type SAVE CURFIT. After the program has been saved on disk, type BSAVE FITCHAR,A\$3F00,L\$P2 in order to save the machine language part of the program.

3. The demonstration plot files may be saved on your slave disk later as described below.

## HOW TO PRODUCE A BACKUP DISK

Author of this program is a scientist who understands your needs for curve fitting tools.

The master disk contains five demonstrations that will introduce you to some of the features of the Curve Fitter program. It is suggested that you try at least one of these demonstrations before attempting to fit your own data. Most of us learn faster by example than by reading a manual. It's also

HOW TO RUN THE DEMONSTRATIONS

All other Control keys are ignored during user input; in this case, use Control Q to stop the program. Control S may be used to stop screen output and Control C will stop the program (unless the program is waiting for user however, Control S may be used to stop screen output and Control C will stop the program (unless the program is waiting for user input); in this case, use Control Q to stop the program). All other Control keys are ignored during user input;

Control Q is the signal to quit the program entirely and return to BASIC.

Control Z may be typed at any time to escape from the normal sequence of prompting questions and jump to the SAVE FILES section of the program.

Control A switches the program into the Automatic mode of operation. In Automatic mode, the default values are used instead of user input. This mode ends when any error occurs or when a default value is outside the range of permissible values or when you type any key. The program also switches out of Automatic mode when the SAVE FILES segment of the program is reached.

Control P allows you to select a print device for subsequent output. After the Control P, type the single-digit number denoting the slot occupied by the printer controller or type 0 to restore normal screen output.

Control G switches the program to call a user-supplied subroutine at lines 2900-2999 in order to read a value from a special sensor, such as a spectrophotometer or pH meter or anything else that you can rig up. The sensor value must be returned in variable V0; Your subroutine may scale V0 as appropriate. Currently, subroutine 2900 always returns V0 = 0. When your subroutine returns, the value of V0 is printed on the input line, just as if you had typed it. If you don't like that value, you subroutine returns, the value of V0 is printed on the input line, just as if you had typed it again to input a different sensor value. When the sensor value is satisfied,

you typed and Control X deletes the entire input line. The back arrow key (Control H) deletes the last character that causes special actions by the program. As summarized in Flowchart J, a number of control characters

WRITE UNKNOWN FILE NAME() ? <NONE>  
Now, the program asks:

You should just press RETURN here, since the fitted file can be regenerated easily by the program.  
WRITE FITTED FILE NAME() ? <NONE>  
The next question is:

If you want to save this demonstration, mount your slave disk and type HTWTDATA. Note that if you try to write a file on a write-protected disk, the program will halt because of a WRITE PROTECTED error.  
WRITE STANDARDS FILE NAME() ? <NONE>  
Program next prints:  
stop pushing buttons and pay attention to what we are doing. The

When the program prints \*\*\*\*\* SAVE FILES, it is time to  
twelve men. This first demonstration performs linear least squares fitting and plots a fitted straight line of 100 points.  
The data file HTWTDATA contains the heights and weights of twelve men, this first demonstration performs linear least squares fitting and plots a fitted straight line of 100 points.  
Interpolated weights are printed for men of heights ranging from 61 to 73 inches.  
Then, the unknowns file called HTWUNK is read in and the

control to see the questions. If you want to ignore the  
automatic mode. Remember that automatic mode can be stopped by  
questions and just watch the action, type Control A to enter  
control T to see the graph or type  
At any time, you may just press RETURN and see what happens.  
Alternatively, you may type Control G to see the graph or type  
and read the explanation given later in this manual.  
Some thing, you may look up that question in the table of contents  
how these responses affect the results. If you don't understand  
default values printed after each question and try to understand  
learn how to use the program by example. Since our objective is to  
will automatically fit the curve. Since our objective is to  
you may just press RETURN after each question and the program  
questions will be read from the disk called HTWTFORM. Thus,  
questions, the default values within <> for all of the other  
words, for the first demo will be read from the disk. In other  
file for the first demo should type HTWTFORM, so that the format  
this demonstration, you do not want to load a format file from disk. However, for  
you do not want to load a format file from disk. For  
<NONE> will be entered as your response and this will mean that  
is unrestricted. If you simply press RETURN, the default value  
Since nothing is printed in the range field within (), your input  
READ FORMAT FILE NAME() ? <NONE>

CURFILE or, if the program has already been loaded, just type RUN.  
To start the program, mount the master disk and type RUN  
more fun to learn by example.

The Table of Contents lists each of the prompting questions asked by the Curve Fitter program, in the same order that they are encountered in the program. On the page number listed after each question, you will find a detailed description of the effects of your responses on the outcome. Note that some of the questions are skipped over, depending on previous options that you have selected.

#### DETAILED EXPLANATIONS OF PROGRAM OPTIONS

CUBICFORM uses cubic polynomial least squares to fit some geometric data (CUBICDATA) for the specific heat of water (Y values) as a function of temperature (X values). This problem is discussed in detail through 6, pp. 326-330. In trying polynomial least squares cannot be compared directly to those for polynomial fitting.

GEOMDATA. You could also try an exponential least squares fit or polynomials of degree two or higher to these data. Normally, the standard error of estimate is a good indicator of the quality of the fit. However, since the geometric and exponentiai least squares methods use LOG transformations, their standard error from 9.55E-4 to 2.67E-5 and the apparent fit improved considerably.

STINERFORM uses Stineman interpolation to fit a curve (STINEDATA) having a sharp change of slope and a broad plateau at its peak. You might want to try fitting a cubic spline curve to this data in order to observe how polynomials tend to overshoot in such cases. A polynomial of degree four does quite a respectable job of fitting the data, though. Go ahead and experiment a little.

PEAKFORM shows the results of averaging and smoothing fashions. PEAKFORM collects from an analog to digital converter. A cubic spline interpolation is then used to draw a smooth curve through the scattered points.

TYPE HTWTRORM here, so that all of the responses to questions will be saved on your slave disk. Although the naming of files is completely arbitrary, you might consider adopting our convention of using the FORM suffix for files, DATA for standards, FIT for fitted curves and the UNKN suffix for unknowns.

Since the format file for this demo expects to evaluate unknowns stored in a disk file called HTWUNKN, type this name if you want to save these data.

At this point, the program will print:

WRITE FORMAT FILE NAME(?) <NONE>

TYPE HTWTRORM here, so that all of the responses to questions

The fitted data points are stored immediately following the scaled standards. Only the Y value is stored for each fitted point, because the X interval is always a constant. Although the original input data for the standards may consist of 1, 2 or 3 values per point (see below), the storage format is changed in the SCALE STANDARDS segment, so that separate X and Y values are stored for each standard point. Also, the error bar values are discarded, so that after scaling, each standard point uses two elements of the D array. The X values are stored at element 0 and other even-numbered elements, while the Y values are stored at odd-numbered elements starting with D(1).

Although the original input data for the standards may consist of 1, 2 or 3 values per point (see below), the storage format is changed in the SCALE STANDARDS segment, so that separate X and Y values are stored for each standard point.

All of the data for the standards, fitted curve and the unknowns are stored in a single array called D(1000). This approach minimizes storage requirements. If necessary, you may change the dimension of this array in program line 10, but you must also make the same change in the value of MX at the end of line 10.

Unknowns are stored in a single array called D(1000). This approach minimizes storage requirements. If necessary, you may change the dimension of this array in program line 10, but you must also make the same change in the value of MX at the end of line 10.

#### INPUT STANDARDS (FLOWCHART B)

If you want to load a format file previously stored on the disk, type its name. Optionally, you may append a volume, slot or drive number after the file name (this is also true for all other files used by this program). The default file name for this question is <NONE>, so if you only type RETURN, no format file will be read and the default values will be whatever was previously answered for each question. If you have just started the program by typing RUN, all of the default values are blank, so you will have to type some valid response to each question.

#### READ FORMAT FILE NAME

The easiest way to grasp the overall flow of the program is to look at flow chart A, which shows the major parts of the program and will direct you to one of the more detailed flowcharts B through H for further information. Flowcharts I and J pertain to user input; you should bear in mind that they are relevant whenever you are typing any response. Also, note that the control characters in flowchart J take effect immediately after you type them and they may be typed at any point in the input line. However, these control characters are not included as part of your actual response to the question.

#### USING THE FLOWCHARTS

There are three ways to input data for standards or unknowns:

#### DISK, KEYBOARD OR SENSOR INPUT

Although error bars are not used by this program, this option is included in order to maintain compatibility with data files used with the Scientific Plotter program sold by Interactive Microware. If you want to use this program to enter raw data to this question. In this case, you will be asked to type Y which will later be plotted by Scientific Plotter, you may type Y to enter a " +/- ERROR" value after each Y value.

#### ERROR BARS (Y:N)

Here, you should give the value of the constant interval between X values.

#### X INTERVAL

If you answered No to the last question, it means that only Y values will be entered, with constant intervals between X values. In this case, you should now type the X value of the first point.

#### FIRST X VALUE

Type Y here if both X and Y values are to be entered for each point. The next two questions are asked only if you type N.

#### X,Y PAIRS (Y:N)

If you have previously entered some data for standards, this question will be asked. The default is always set to No. You should type Y here if you wish to retain the last set of standards and you don't want to make any deletions or changes of scale. In this case, the program skips to the LIST STANDARDS question.

#### SAME STANDARDS (Y:N)? (N)

In summary, the total size required for array D may be calculated by doubling the number of standards, adding the number of fitted points and then adding the number of unknowns (times two if multipliers are needed).

The data for the unknowns is stored right after the fitted data, and either one or two elements in array D are required for each unknown, depending on whether a different multiplier value is required for each unknown.

If you are reading data from a disk file, this question allows you to skip over some of the points and read only selected points. Type 1 if you want to read every point, type 2 to read every second point and so on.

#### INTERVAL BETWEEN POINTS

This question is asked only if you are reading data from a disk file. In some cases, you will only want to plot some of the points from a larger data file. Enter 1 (one) to start reading at the first point to be read. If so, enter the number of the first point to be read. Notice that since you have already read the first value, Enter 1 (one) to start reading at the first value. The program can automatically calculate the position of the first requested data point in the file.

#### FIRST POINT TO BE USED

The following general method may be used to store data on disk for later editing by this program:

```
1000 CD$=CHR$(4):P$="PIMDATA"
1010 PRINT CDS;"OPEN ";P$;PRINT CD$: "WRIT
1015 PRINT NUM: REM NUMBER OF DATA VALUES
1020 FOR I=0 TO D(0): PRINT D(I):NEXT
1030 PRINT CDS;"CLOSE ";P$;
Between statements 10 and 1000, you could insert any program that stores data values in array D.
```

It is easy to create data files that are compressible with curve fitter. Just be sure that the data are stored as a text file in the format described above under the heading INPUT STANDARDS. Data stored on the disk by the APPLAB Data Acquisition System, Scientific Plotter and other programs available from Interactive Microware, Inc. are directly compressible with Curve Fitter.

If you wish to input data from a disk file, type the name here. Otherwise, type NONE in order to skip over this part of the program.

#### READ FILE NAME

You may type the values on the keyboard, or you may read the data from a disk file, or you may input values from a special sensor, such as a spectrophotometer or pH meter. As explained above (see CONTROL CHARACTERS FOR EDITING AND PROGRAM CONTROL), sensor input is a special case of keyboard input. You merely type Control Y to enter the sensor value on the input line.

From this point on, your standards data are always stored in the D array as X, Y pairs, even if you entered only Y values at

The reason for this question is that the least squares fitting routines always assume that the major errors in the X values and that the X values in your input data are mostly negative.

#### INTERCHANGE X & Y DATA (Y:N)

In this segment of Curve Fitter, the standards data will be rearranged in the D array, sorted by ascending X value and scaled according to your instructions. Also, deleted values and error bars will be discarded. If you want to save your original bar values will be discarded. If you enter last chance, as announced by the input data on disk, this is your last chance, as announced by the message, TYPE CONTROL Z NOW TO SAVE RAW DATA. The program goes on to print the next question, but you can type control Z anytime before processing RETURN.

#### SCALE STANDARDS (FLOWCHART C)

If it is possible to use this keyboard input routine to edit data for standards or unknowns entered previously. To do this, type Control Z at any point and skip through the program until you come to the INPUT STANDARDS or EVALUATE UNKNOWN segment. Then, answer the questions as though you want to type the data on the keyboard. Since the previous values are now the defaults, you can scan through the data by pressing RETURN after each question (or type Control A), until you come to a value that needs to be edited. After all corrections have been entered, type Control A to scan to the end of the data.

If you type Control Y, the sensor value calculated by subroutine 2900 will be printed as your response and you may simply press RETURN. If you type 10000, that point will be deleted later. When you type 9999, this signals the end of the input data. If you really want to include the value 9999 or 10000 in your data, type 9999.001 or 10000.001 instead.

If you have selected keyboard or sensor input, the program prints POINT 1, and then asks for X, Y and +/- error appropiate. If you are inputting unknowns, the +/- ERROR message will be replaced by MULTIPLEXER. The default value will be the value previously stored at that position in the D array. The purpose of this feature is to make it convenient for you to edit your data. If the default value is correct, just press RETURN.

Unless the standards have already been plotted, you should

PLOT STANDARDS (Y:N)

At this point, you may get a listing of the transformed data by answering Y. To direct the output to a printer, type Control-P, followed by the slot number of the printer controller, before pressing RETURN.

LIST STANDARDS (Y:N)

LIST AND PLOT STANDARDS (PLOWCHART D)

These conversions on the Y values are carried out in exactly the same way as those of the X values (see above).

Y LOG SCALE

Y OFFSET

Y SCALE FACTOR

If you type LOG or LN in response to this question, the base 10 or base e logarithm of X will replace the value of X calculated above. If no logarithmic conversion is desired, type N as your answer.

X LOG SCALE

X=SCALE\*(XINPUT+XOFFSET)

This allows you to add a constant offset to each X value, for instance, if your X values range from 10000 to 10001, you could enter -10000 here so that the plotted values will range from 0 to 1. If no offset is desired, type 0. The plotted X value is now calculated by the formula:

X OFFSET

You may now enter a scale factor, which will multiply each X value. If no scaling is required, type 1 (one).

X SCALE FACTOR

Constant X intervals. This makes it possible to delete bad points (outliers) in the later case.

You now have the choice of discarding the averaged points (by typing N) or accepting them as the new standards (by typing Y). If you type N, the averaged points are erased and the program returns to the # POINTS AVERAGING question, so you can make a different choice. If you type Y, the old standards are erased and the averaged points take their place in all subsequent calculations. You will note that #/2 points at each end of the x axis are averaged points that are taken from the original data.

#### MAKE PERMANENT (Y:N)

After the averaging process is completed, the averaged values are plotted with + symbols to distinguish them from the original points, which are denoted by square symbols. You should type Control G to see the graph. Control G to see the graph. After the averaging process terminates permanently.

If you type 0 or 1 as your response, no averaging will be done. If you type 2, the first and second X and Y values will be averaged, so will the third and fourth values, and so on. The number of points will be divided by 2. Similarly, if you answer 3, groups of 3 points will be averaged and the number of points is divided by 3. The original values are lost, since the averaged values are stored above the standards in the array. Each averaged point requires two elements in the array and it is inefficient space is available, the message OUT OF ROOM is printed and the averaging process is stopped above the standards in the array.

The usual reason for averaging your data is to decrease the number of standards, while retaining the "flavor" of all of the data points. If you don't want to reduce the number of points and your primary purpose is to smooth random errors, you should use the smoothing option, instead. Of course, you could also reduce the number of standards by just skipping some of the values during data input, but this ignores all information about intermediate values.

#### # POINTS AVERAGING

#### AVERAGING AND SMOOTHING (FLOWCHART E)

Next, the program plots the standards, always using the small box symbol. Bear in mind that you can view the graph by typing Control G and return to Text mode by typing Control T.

Labels for the x and y axes. At the top end of the y axis and at the right end of the x axis, the letter B is printed, followed by a number. This stands for the exponent of ten for each of the labels on the axes. For example, the label 12 with exponent E2 would have the value 1200. Likewise, a label of 9 with exponent E-1 means 0.9 and E60 means 8.

The right end of the x and y axes. At the top end of the y axis and at the right end of the x axis, the letter B is printed, followed by a number. This stands for the exponent of ten for each of the labels on the axes. For example, the label 12 with exponent E2 would have the value 1200. Likewise, a label of 9 with exponent E-1 means 0.9 and E60 means 8.

Labels for the x and y axes. At the top end of the y axis and at the right end of the x axis, the letter B is printed, followed by a number. This stands for the exponent of ten for each of the labels on the axes. For example, the label 12 with exponent E2 would have the value 1200. Likewise, a label of 9 with exponent E-1 means 0.9 and E60 means 8.

This allows you to select one of three different symbols for

NEXT SYMBOL

### CURVE FITTING (FLOWCHART F)

If you type N here, the smoothed points are erased and the program returns to the # POINTS SMOOTHING question so that you can make a second choice. The answer X causes erasure of the previous standards and the smoothed points become the new standards. As a consequence of the fact that both X and Y values of each point are averaged,  $(\bar{x})/2$  points disappear at each end of the X axis. If you wish to keep the range of X values the same as before, you could skip to the INPUT STANDARDS part of the program and append the original standards at the extremes of the X axis. Of course, these points no longer carry the same weight as the smoothed points.

MAKE PERMANENT (Y:N)

After smoothing, the smoothed values are plotted using the symbol, which is easy to spot among the box symbols used for the standards. Type CONTROL G to see the graph.

If you respond by typing 0 or 1, no smoothing will be done and the program will skip to the Curve Fitting segment. If you type 2, the first and second X and Y values are averaged, and so are the second and third, third and fourth, etc. Note that this reduces the number of points by 1, where # is your response to the # POINTS SMOOTHING question. Here's another example: if you type 3, the first, second and third X and Y values are averaged, as are the second, third and fourth, etc. The original standards are not lost, because the smoothed points are stored above the elements unless there is no more room in the D array; in this event, the OUT OF ROOM warning is printed and the smoothing process ends immediately.

The purpose of smoothing is to reduce random variations in the data values by averaging two or more successive values. You will find that small peaks in the graph tend to disappear after averaging. It is up to you to decide whether the small peaks are just "noise" or whether they are real effects.

The fact that both the X and Y values for each point are averaged. This is a natural consequence of axes disappear after averaging. This is a natural consequence of

# POINTS SMOOTHING

Your response to this question determines how many points will be plotted for the fitted curve. It is a good idea to request relative few points at first, while you are searching for the best fitting method, because the calculation time increases for more points, especially in the case of polynomial fitting. However, the evaluation of unknowns becomes more accurate with increasing number of points (see EVALUATE UNKNOWNNS). Thus, after you select a fitting method, you should repeat the calculation using a larger number of points, consistent with the desired degree of accuracy.

# OF POINTS ON CURVE

If you type N to this question, the program skips to the SAVE FILES segment of the program. If you type I for Interpolation, the program prints AVERAGING DUPLICATE VALUES because the same X value. However, the least squares methods do allow interpolation methods do not allow more than one point with the same X value. In other hand, if you assume that there are random errors in the Y values, least squares fitting is the logical choice (type I). On the other hand, if you are confident that your equations selected for fitting. If you are limited to the standard deviations are accurate, interpolation is the reasonable choice (type II). Other considerations affecting this decision are discussed below under THEORETICAL CONSIDERATIONS.

OF CURVE FITTING.

Curve Fitter allows you to produce a curve through your points in two conceptually different ways: interpolation and least squares fitting. An interpolated curve always exactly passes through each standard point, whereas a least squares curve minimizes the sum of the squares of the distances between the curve and the standard points. In other words, a least squares fitted curve passes as close as possible to the standard points, subject to the limitations of the equations, a least squares fitted curve and the standard deviations are accurate, interpolation is the reasonable choice (type II). Other considerations affecting this decision are discussed below under THEORETICAL CONSIDERATIONS.

#### INTERPOLATION OR LEAST SQUARES FITTING

Several alternative fitted curves.

Plotting the next fitted curve. Symbol 2 is a point (.), symbol 3 is a plus sign (+) and symbol 4 is a cross mark (x). The standard cards are always plotted using the square, symbol 1, so that they can be distinguished from the curve, symbol 1, so that they can be distinguished from the curve, symbol 2 is the best choice, but you may want to choose a different symbol so that you can see the differences among different symbols.

If you have selected polynomial interpolation, you must now select the degree of the equation to be used. A degree of 1 yields linear (*straight-line*) interpolation, as expressed by the formula  $y = A + Bx$ . Here,  $A$  is a constant and  $B$  is the slope of the line. A degree of 2 produces a quadratic curve,  $y = A + Bx + Cx^2$ . For each successive higher degree, an additional term is added to the equation, consisting of a new constant multiplied by the previous term.

#### Degree of Polynomial

In the course of developing this program, I arranged to investigate the Neville's iteration method, Lagrange interpolation, and Newton-Raphson method. In many cases, the Stineham curve is not very different from linear interpolation. In fact, in many cases, the departure from standard points is well protected against underrashon. This method is often below the standard curve in an oscillate above and below the standard curve in an intermediate curve. In these cases where an abrupt change of slope occurs in the Stineham curve is not very different from linear interpolation. My experience is that a Stineham curve seems to fall somewhere between a linear (*straight-line*) interpolation and a cubic interpolation. The maximum number of standards to be fitted is again limited to the value of ABC (line 12) plus 1. The calculation time is about the same as that for a cubic spline in this program.

In the course of developing this program, I arranged to investigate the Stineham method of interpolation. It is described in creative computing magazine, July 1960, pp. 54-57. It is especially well suited for cases where an abrupt change of slope occurs in the arrays A, B and C at the end of line 12) plus 1, the message TOO MANY STANDARDS is printed and the program returns to the beginning of the CURVE FITTING segment. Although the results obtained with the cubic spline method are very similar to those obtained with the polynomial method, the cubic spline is significantly faster.

The cubic spline method fits a cubic polynomial through each four successive points and saves three coefficients for each pair of standards. These coefficients are stored in arrays A, B, and C, which are dimensioned in line 12. If the number of standards exceeds the value of ABC (set equal to 99, the dimensions of arrays A, B and C at the end of line 12) plus 1, the message TOO MANY STANDARDS is printed and the program returns to the beginning of the CURVE FITTING segment. Although the results obtained with the cubic spline method are very similar to those obtained with the polynomial method, the cubic spline is significantly faster.

Polynomial interpolation includes linear, quadratic, cubic and higher order polynomials fitting up to degree 6. A polynomial of degree  $N$  is calculated for  $N+1$  standards spanning each interval point. This is the slowest method of the three, particularly for higher degrees.

If you have chosen 1 for interpolation above, you now have a choice of three methods:

After completion of the least squares fitting, the coefficients of the equation and several measures of the reliability of the fit are printed. A good discussion of these coefficients of the least squares fittings of the data points is given in reference 1, pp. 260-275. The coefficient of determination is given in reference 1, pp. 260-275. The coefficient of determination is the proportion of variation of  $y$  that is explained by linear regression on  $x$ . Its value ranges from 0 to 1; a value close to 1 indicates a strong linear relationship between  $x$  and  $y$ . The coefficient of correlation is the square root of the coefficient of correlation between  $x$  and  $y$ , while a value of 0 means there is no linear relationship. The coefficient of correlation between  $x$  and  $y$  is its value ranges from 0 to 1 and may be interpreted similarly. If its value is 1, there is a perfect linear relationship between  $x$  and  $y$ . The standard error of estimate is a measure of how much the values are likely to vary this much from the calculated value. In other words, multiple experimental observations at this value of estimated error from the fitted curve deviate from those observed. In standard error of estimate is a measure of how much the values are likely to vary this much from the calculated value.

Polyynomial least squares attempts to fit the standards by an equation of the form  $y = a + b*x + c*x^2 \dots$ , where the number of terms is  $n+1$  and  $n$  is the selected degree of the equation. This is done by solving a system of simultaneous equations involving derivatives of the error equations with respect to the  $n+1$  coefficients. The solution is found by the method of Gaussian elimination, as described in reference 2, pp. 155-175 and pp. 324-330.

Exponential least squares assumes that the standards conform to an equation of the form,  $y = a * \exp(bx)$ . This equation can be linearized by taking the log,  $y_{\log} = \log y - \log a + b*x$ . This transformed equation is then fit by linear least squares.

Geometric least squares applies an equation of the form  $y = a * x^{1/2}$  to the standards. This is accomplished by using a log transformation of the former equation,  $\log y = \log a + b * \log x$ . This transformed equation is then fit by linear least squares.

Linear least squares fits the best straight line through a set of standards, using the equation  $y = a + b*x$ . Although this is a special case of polynomial least squares with degree 1, it is computationally convenient to treat it separately.

If you have chosen linear least squares fitting, you will now select one of these four methods:

#### LINEAR, GEOMETRIC, EXPONENTIAL OR POLYNOMIAL LEAST SQUARES

Next power of  $x$ . The largest degree allowed by the present program is 6, because numerical errors increase rapidly at higher degrees and calculation time becomes excessive. If the number of standards is fewer than 7, the maximum degree allowed is one less than the number of standards.

The equations used to calculate the fitted curve are suited for calculating  $y$  values for a given  $x$ . However, it is often desirable to calculate  $x$  values for a given  $y$  and therefore, this program calculates unknowns directly from the fitted curve, rather than using the exact equations. In other words, unknowns are evaluated by linear interpolation between the closest pair of points on the fitted curve. In regions where the fitted curve is linear (e.g., for the case of linear extrapolation or least squares), this approach gives exactly the same value as you would obtain from fitting a quadratic equation. However, in curved regions of the curve, the fitted curve will be a small discrepancy. As you increase the number of points on the fitted curve, the error is decreased. With 100 or more points on the fitted curve, the error is generally negligible. If greater accuracy is required, the error is generally negligible. If greater accuracy is required, the error is generally negligible.

#### EVALUATE UNKNOWNS (FLOWCHART G)

If you answered N to the last question, you have the option of erasing the last fitted curve. The program then recycles to the beginning of the Curve Fitting segment so that you may choose a different fitting method.

ERASE FITTED CURVE (Y:N)

This question appears after any of the fitting methods has completed its calculations and the fitted curve has been plotted (type Control G to see it). You are the final judge of whether the fit is satisfactory. If you type Y, the present curve will be used for evaluating unknowns.

SATISFACTORY (Y:N)

If you have selected polynomial least squares, you must now type the degree of the polynomial. In general, you should choose the lowest degree that gives a decent fit. Curve fitting makes it easy for you to try several possibilities. If you have a good theoretical reason to expect an equation of a particular degree, don't yield to the temptation to choose a higher degree.

Remember that with a polynomial of degree  $N-1$ , you can exactly fit a group of  $N$  points. Thus, the program only allows an  $N-2$  degree polynomial. Also, if the number of standards is fewer than 4, the program prints TOO FEW STANDARDS and forces a different choice of method. The maximum degree allowed is 6.

Because accuracy is limited at higher degrees and the calculation time becomes excessive.

### DEGREE OF POLYNOMIAL

You may want to turn on your printer at this point by typing Control P and the slot number. The only acceptable response to this question is Y, so type Y when you are ready for a listing of the results. The number of the unknown is printed for a list of column 4, the input value, the calculated value and finally, in column 1, followed by the input value, the calculated value and finally, in column 4, the unknown is converted to the standard form. Next, the scaled input value is compared with the transformed.

## READY FOR LISTING

Input of unknowns is the same as inputting standards (see DISK, KEYBOARD OR SENSOR INPUT). Again, the data may be entered from disk, keyboard or a special sensor (type Control Y) and the previous values in the array become the entry by typing 1000; the entries. As before, You may delete an entry by typing 1000; the sign that you have entered the last value is 9999. If the array is full, the OUT OF ROOM message will be printed and no more input will be allowed. However, you will have a chance later to enter more unknowns.

## X VALUE, Y VALUE, MULTIPLIER

In many cases, the samples for the unknowns are prescaled in some way so that the measured values fall within the range of the standards. If the prescaling multiplier is the same for all samples, type its value. Each factor interpreted X or Y value will be multiplied by this factor before it is printed (in the VALUE column). If no scaling is required, type 1. If the prescale value varies for different samples, type 0 and then you will be asked to enter a separate multiplier for each unknown.

## MULTIPLIER; TYPE 0 IF VARIABLE

Now, you may select the axis of interpolation. Either X or Y values may be entered and the complementary Y or X value will be interpolated from the fitted curve.

## ENTER X OR Y VALUES

If you answer N to this question, the program skips to the SAVE FILES segment.

## INPUT UNKNOWN VALUES (Y:N)

Coefficients printed by the program and the appropriate fitting equation. This will also be necessary if you want to extrapolate values outside the range of the standards.

fitted curve. If it is outside the range of the fitted curve, the OUT OF RANGE message is printed. Otherwise, the corresponding value is interpolated on the other axis. This result is multiplied by the specified fitted multiplier and the final result is printed in the VALUE column.

Let's go through a simple example which will help to clarify standards:

All of this. Suppose that you have entered the following

POINT	X =	Y =	SCALED X	SCALED Y
1	1	1	2	2
2	2	2	2	2

The last 2 columns show the values actually plotted if we assume that you specified an X offset of 1 and a Y scale of 2. For simplicity, we'll select interpolation with a polynomial of degree one; that is, a straight line from  $x, y = (2, 2)$  to  $(3, 4)$ . Next, we'll enter some X values with variable multipliers and calculate the unknown Y values.

That last 2 columns show the values outside the graph. Note that the X value that is printed is the scaled value, so that you can refer it to the graph.

Now, you have the opportunity to enter more unknowns or edit the previous ones. If you type Y, the program returns to the BENTER X OR Y VALUES question.

By typing Control Z, you may exit to this part of the program at any time in order to save your standards, fitted curve, unknowns or a format file on disk. In all cases below, the file name defaults to NONE, so you may simply press RETURN if you don't want to save a file. This provides an extra measure of protection against accidentally overwriting a file that you wanted to keep. Also note that the automatic mode of operation terminates at this point so that you may save your files as needed to keep.

Also note that the disk operating system saves your files as necessary. Typing Control D sends the entire preceding input line to the disk operating system. For example, to list the catalog of drive 2 in slot 6, you should type CATALOG,S6,D2

followed by Control D. Therefore, all disk I/O will use the same drive.

#### SAVE FILES (FLOWCHART H)

#### MORE UNKNOWN (Y:N)

POINT	INPUT X	MULTIPLIER	SCALED X	Y =	VALUE	POINT	INPUT X	MULTIPLIER	SCALED X	Y =	VALUE
3	2.5	3	3.5	3.5	OUT OF RANGE	3	3.0	8	8	8	2
2	2.0	2	3.0	4	OUT OF RANGE	2	2.5	3	3	1	1
1	1.5	1	2.5	3	OUT OF RANGE						

The printed report for this session would be as follows:

the printed report for this session would be as follows:

Now, you have the opportunity to enter more unknowns or edit the previous ones. If you type Y, the program returns to the BENTER X OR Y VALUES question.

By typing Control Z, you may exit to this part of the program at any time in order to save your standards, fitted curve, unknowns or a format file on disk. In all cases below, the file name defaults to NONE, so you may simply press RETURN if you don't want to save a file. This provides an extra measure of protection against accidentally overwriting a file that you wanted to keep.

Also note that the disk operating system saves your files as necessary. Typing Control D sends the entire preceding input line to the disk operating system. For example, to list the catalog of drive 2 in slot 6, you should type CATALOG,S6,D2

followed by Control D. Therefore, all disk I/O will use the same drive.

If you answer Y to this question, the screen will be erased and the program will start over without erasing the screen. If you type N, the program will compare the fitted curve to the original curve obtained before you want to edit the standards (delete or add a point) and then start over.

#### ERASE GRAPH (Y:N)

Now, you may save the current list of default responses to all questions as a format file. Later, if you want to carry out a similar fitting operation, just enter the name of this format file after the READ FORMAT FILE NAME question and from there on, you may simply press RETURN after each question where the default value is satisfactory.

#### WRITE FORMAT FILE NAME

This option permits you to save the data for the unknowns in the same form as you entered it (that is, unscaled). In this form, you may read the unknowns from disk instead of reyping them at a later time. The text file will contain the number of unknowns as its first value and then the input values. If you have entered multtiples for each unknown, the first value is the number of unknowns times 2, followed by the input value and then the number of unknowns for each unknown, the first value is the first value of the multipple for each point.

#### WRITE UNKNOWN FILE NAME

You may also save the fitted data. This option is useful for transferring the results to the Scientific Plotter program for producing a professional-looking graph. The data is saved as a text file containing a fixed X interval, starting with the X value produced at a fixed X interval, until recall that fitted data is always value for each point. You will recall that fitted data is always standard having the smallest X value. For future reference, the standard having the next X value is the X value of the standard having the next X value. For subsequent entry in the Scientific Plotter program.

#### WRITE FITTED FILE NAME

If you enter a valid file name here, your standards will be saved on disk. The first value in the text file is the number of points times 2, followed by the X and Y values for each standard. Remember that if you have scaled or offset the data or converted it to log form, the data will be stored in the converted form. It is to circumvent this, type Control Z immediately after entering the data.

#### WRITE STANDARDS FILE NAME

The usual reasons for fitting curves to data are to obtain theoretical formulation or calibration curves or to confirm a hypothesis with a graph usually looks model. Another reason comes to mind; a graph usually looks better when the observed points are connected by a curve of some sort. However, we must be careful not to be misled into thinking that we know more than we do about the values lying between the points without a sound basis in theory may represent only wishful observations. Curves drawn through a small number of observed points will be different from those drawn through a large number of points. A much more detailed treatment will be found in the books listed under REFERENCES, which I have found particularly useful.

#### THEORETICAL CONSIDERATIONS OF CURVE FITTING

If you enter error bar values in Curve Fitter for later use with Scientific Plotter, you must save the standards at the very beginning of the Scale Standards segment, because after that, the error values are deleted. Also, if you have entered only Y error values, the data are expanded to include both X and Y values in the D array. Thus, the format of the standards file saved on disk will be different after the Scale Standards segment.

Together with the standards by reading the saved disk files into Scale Fitter, you may produce a fitted curve and then plot the fitted curve, you may produce a fitted curve of entering data in Curve Fitter is that Plotter. The advantage of entering data in final form by Scientific Plotter is that data which will later be plotted in final form by Scientific Plotter with Microware. Thus, you may use Curve Fitter to enter compatible with the Scientific Plotter program, also sold by Interactive Microware.

#### USAGE WITH SCIENTIFIC PLOTTER

The formats of the standards file and fitted file are changed by editing. If the range of the X and Y values is not changed by editing, the axes plotted when you answer N to the PLOT STANDARDS question will coincide with the original axes. If the range is changed by editing, you may set all compare the fitted curves if you answer N to the PLOT STANDARDS question. However, in this case, the edited standards and out of range values will not appear on the graph.

A polynomial curve of degree  $N$  can have, at most,  $N-2$  inflection points. Therefore, if it is clear that an inflection point is needed to give a reasonable fit to your standards, you should use a polynomial of degree 3 or higher.

Interpolation methods seek to exactly fit a set of standard points and altogether ignore the possibility of inherent errors in the data. A polynomial equation of degree  $N+1$  fits  $N+1$  points exactly; however, the solution is unique. However, if the data set includes more than  $N+1$  points, the shape of the curve will be affected by the choice of which set of  $N+1$  points are used to define the interval. This program uses the same number of points in either side of the two adjacent points and the last few points in the set of standards are necessary to give a given interval. Insofar as possible, this program uses fewer points of the interval to define the curve. It will be affected by the shape of the curve at the ends of the fitted curve.

Interpolation

If the conditions of the experiment are continually changing there is less justification for averaging, even if we are sure that random errors are present. In this case, we must compare the magnitude of the random errors to the magnitude of the individual noisy measurements. However, if the signal is nonlinear, the averaged curve will be distorted to some extent by averaging and thus, averaging should be considered only when the value of the error is greater than the change in the signal. Smaller considerations apply to the underyling signal. Similalr considerations apply to the magnitude of the error of the averaged curve than the change in the signal, which is just an averaging technique that does not smooth the number of data points.

Average and Smoothing

All experiments naturally measure certain amounts of error, including systematic errors, which affect all measurements in the same way, and random errors, which may either increase or decrease the observed value. It is up to the experimenter to detect and correct systematic errors, but this program can help you to deal with random errors. If we make a large number of "identical" measurements, the average of all measured values will be closer to the "true" value than are most errors in the individual measured values, because some of the random errors are negative direction. In the absence of contraray evidence, we shall assume that the random errors follow a normal distribution, or bell-shaped curve, since this is true of most natural processes.

A useful guideline for choosing the form of equation to be used for least squares fitting is that it is wise to choose an equation with the least number of constants. If two different equations give about the same standard error of estimate, choose the simpler one; that is, choose linear over exponential or quadratic.

In the cases of geometric and exponential least squares fitting, we actually minimize the sum of the squares of the deviations of  $\log y$  from the curve, rather than using the deviations of  $y$  values themselves. Thus, the statistical arguments in favor of least squares fitting are weakened for these cases. Nevertheless, these methods do appear to give good results for some curves. Exponential least squares is suggested when a plot of  $\log y$  versus  $x$  appears to be linear, whereas geometric least squares works well when a plot of  $\log y$  versus  $x$  is linear.


Curve and another series of points will be below the fitted line; that is, a series of points will all be above the fitted line. A breakdown in assumption 5 may manifest itself by a curvature. A breakdown in assumption 5 may manifest itself by a magnitudes of the deviations from the fitted curve may show points near the center. In other cases, a plot of the  $x$  axis will tend to deviate more from the fitted curve than may show up in the fitted curve; points toward the extremes of should produce a bell shaped curve. A defect in assumption 3 or the frequency distributions of the magnitudes of the deviations of the errors in  $y$  are randomly distributed, a histogram of probable solution" (Ref. 1, p. 314). Also relevant to assumption 2, if the constant variance, then [least squares] produces the most frequent values in the  $y$  values follow any distribution with statistical errors in the  $y$  values follow any distribution with assumption 2 is softened by the knowledge that "if the average scatter of the  $x$ 's from their mean" (Ref. 3, p. 32). Can be used safely if the variance of  $x$  is less than a tenth of first assumption, a rule of thumb is that "least squares analysis most probable fit, according to statistics. Regarding the deviations of the observed  $y$  values from the fitted line produces under these conditions, minimizing the sum of the squares of the


of measurements at other values of  $x$ .  
5. The  $y$  values are randomly sampled at each  $x$  and independent  
4. The population mean of  $y$  is a linear function of  $x$ .  
3. The population variance of  $y$  is the same at each value of  $x$ .  
2. The errors in  $y$  values are normally distributed at each  $x$  value.  
1. The  $x$  values are free of sampling and measurement errors.

Assumptions are common to all of these methods:  
is inappropriate, due to the presence of relatively large random errors in the measured values. The following important assumption is useful in cases where interpolation


- that the standard error for geometric and exponential fits is affected by the log transformation, so it cannot be compared to the standard errors for other methods.
- Curve Fitter provides facilities for editing your data and removing "bad" points (outliers). But how can you decide whether a point is bad? The most immediate indicator is that the distance of that point from the fitted curve is much greater than the significant effect on the curve of other points. A large deviation can have a significant effect on the curve, because we are minimizing the squares of the deviations. Bad points at the extremes of  $x$  will significantly affect the slope of the curve. After a slope than on the position (height) of the curve. After reviewing the experimental conditions when the bad point was measured, you may be able to justify throwing it out. Physically impossible values or samples measured prior to attachment of equipment are clear candidates for elimination. More sophisticated tests for detecting outliers are mentioned in reference 3, p. 127.
- The methods included in Curve Fitter are the most widely used methods and work well for most cases, but there are also many cases where special techniques are needed regressed (see ref. 3, pp. 267-337).
- Another limitation of the methods presented here is that they do not work for equations containing more than one independent variable. In such cases, one often designs experiments such that only one variable changes while all others remain constant. Under these conditions, our methods are applicable. However, you can produce a curve with any possible shape by altering two or more independent variables at the same time. In such cases, (Prindle-Hall, Inc., Englewood Cliffs, NJ) 1970.
1. R. D. Remington and M. A. Schork, "Statistics with Applications to the Biological and Health Sciences" (Prentice-Hall, Inc., New York) 1972.
2. W. S. Dorn and D. D. McCracken, "Numerical Methods with FORTRAN IV Case Studies" (John Wiley and Sons, Inc., New York) 1970.
3. C. Daniel and F. S. Wood, "Fitting Equations to Data" (John Wiley and Sons, Inc., New York) 1980.









## **Smooth and Averaging Flowchart**







## **Flowchart D List and Pilot Standards**





Flowchart for  
Curve Fitting



If you own a SILENTYPE printer, the changes described below will enable you to print your graphs at the touch of a key. Also, you will be able to print the series of requests and answers that produced the graph, tables of results and other information that you wish to save.

First, LOAD SCIPLOT or CURFIT and type the following changes exactly:

```

2852 IF C = 16 THEN GET C$: PRINT : PRINT C0$ + "PR#" + C$: PRINT CHR$
2853 (20): POKE - 12529,0: GOTO 2810
2856 IF C = 17 THEN POKE - 12529,255: POKE - 12528,7: POKE - 12525,64
2858 : POKE - 12524,0: PRINT CHR$(17): GOTO 2810
2858 IF C = 18 THEN TEXT : END

```

Now, SAVE this modified version on your own disk (do not remove the write protect tab from the original disk).

When you RUN the modified program, you may type CTRL P, followed by a single digit number that tells what slot your SILENTYPE interface card is in. For example, CTRL P1 would select slot 1. From this point on, the questions and answers should appear both on the screen and on the printer. If the screen display (echo) is off, type CTRL P again; each time you type CTRL P (#1-7), the screen echo switch is toggled, just as though you had typed CTRL T. You will note that when the screen echo is off, some of the tabs printed by CURVE FITTER do not TAB correctly; in this event, repeat the CTRL P command.

After the printer is activated (by CTRL P), you may print your graph by merely typing CTRL Q. To stop the program, use CTRL R instead of CTRL Q.

## CHANGES FOR USE WITH SILENTYPE PRINTER

### SCIENTIFIC PLOTTER AND CURVE FITTER

Interactive Microwave, Inc.  
P.O. Box 771  
State College, Pa 16801  
(814) 238-8294



Interactive Microwave, Inc.  
P.O. Box 771  
State College, Pa 16801  
(814) 238-8294



#### CURVE FITTER UPDATE #1

1. You may increase the number of data values stored in CURFIT by changing the DIMENSION of array D(1000) in Line 10 to D(2000). At the end of Line 10, you must also change the value of MX to the same maximum dimension (MX=2000).
2. You may increase the maximum number of standard points for the cubic spline and Stineman interpolation methods by increasing the DIMENSIONS of arrays A(99), B(99), and C(99) in Line 12. In this case, you must also increase the value of ABC at the end of Line 12 by a corresponding amount.

If you get an OUT OF MEMORY error, you will have to decrease the size of these arrays or else use a smaller dimension for the D(2000) array.

The extrapolation factor widens the margins around the standards in the plotted curve. For example, an extrapolation factor of 0.5 adds 50% of the range of the standards on the left, right, top and bottom margins. You must always enter an extrapolation factor of 0 when using an interpolation method instead of a least squares fitting method.

$$860 \text{ XY} = 2:\text{DD} = 2:\text{DD}(1,1) = \text{DD}(0,1) + \text{IV}:\text{DD}(2,1) = 1: \text{IV}^*:9999 \\ \text{DD}(3,1) = 0:\text{DD}(4,1) = \text{X}_0:\text{DD}(5,1) = (\text{X}_1 - \text{X}_0) /$$

$$585 \text{ Y2} = (\text{Y1} - \text{Y0}) * \text{EX}: \text{Y0} = \text{Y0} - \text{Y2}: \text{Y1} = \text{Y1} + \text{Y2}: \text{Y2} = \text{Y1} - \text{Y0}: \text{XY} = (\text{Y1} - \text{YB}) / \text{Y2}$$


$$480 \text{ X2} = (\text{X1} - \text{X0}) * \text{EX}: \text{X0} = \text{X0} - \text{X2}: \text{X1} = \text{X1} + \text{X2}: \text{X2} = \text{X1} - \text{X0}$$

#### 470 INPUT "EXTRAPOLATION FACTOR (0:1) ?"; EX

These changes to permit extrapolation:  
 Quarantine that extrapolating the fitted curve will give a reasonable prediction of results. At your own risk, you may make squares curve, with some caution. However, it is sometimes valid to extrapolate a least squares curve. However, it is sometimes outside the range of the standards data. Nevertheless, it is sometimes valid to extrapolate a least squares curve, with some caution. Quarantine the fitted curve will give a reasonable prediction of results. At your own risk, you may make these changes to permit extrapolation:

#### CURVE FITTER UPDATE #2

Interactive Microwave, Inc.  
 P.O. Box 771  
 State College, Pa 16801  
 (814) 238-8294



2. If you perform logarithmic conversion on your X or Y data for your standards, the original version of Curve Fitter reports the interpolated results for the unknowns in logarithmic form. The changes below will convert the results for the unknowns back to the antilog form.

1890 Z2 = D \* (P0 - U + (Z1 - D(P0)) / (D(P2) - D(P0)))  
+ W: IF XG THEN Z2 = EXP (Z2 / XG)

1895 GOTO 1945

1920 Z2 = (Z0 - INT (Z0)) \* (D(P0 + 1 + EB) - D(P0)) +  
D(P0): IF YG THEN Z2 = EXP (Z2 / YG)

1925 GOTO 1945

The changes below assume that you are using either the EP-12 parallel interface card (made by Interactive Structures, Inc.) or the GRAPPLER(tm) interface card (made by Orange Micro, Inc.).

The changes below assume that you are using either the EP-12 scientific Plotter and Curve Fitter, or the new EP-12 card because it has special commands to print low resolution graphics, half-tone graphics, super high resolution graphics (960 x 792 points) and special characters and symbols defined by you. The EP-12 interface cards, we highly recommend the new EP-12 card because it also works with Pascal and CP/M systems, and it includes a DEMO DISK showing examples of all features. The price of this DEMO DISK shows a card is only \$175, and it is now available from powerful interface card is \$175, and it is now available from Interactive Microware.

For both Scientific Plotter and Curve Fitter, make the following changes for use with the EP-12 interface:

2852 IF C=16 THEN GET C\$: PRINT CD\$+"PR#"+C\$: PRINT CHR\$(9)"80P": GOT0 2810

2858 IF C=17 THEN PRINT CHR\$(9)"15H": GOT0 2810

2859 IF C=18 THEN TEXT: END

For the GRAPPLER interface, omit the PRINT CHR\$(9)"80P": in line 2852 and change "15H" in line 2858 to "G2". After typing CTRL P, followed by a single digit number denoting the slot that your interface card is plugged into. If the printer is on, you can print the hi-res screen by merely typing CTRL Q. To stop the program, type CTRL R instead of CTRL Q (as in the manual).

\* For the PKASO series of interface cards (by Interactive Structures, Inc.), change "80P" to "I" and change "15H" to "33H".

CHANGES IN SCIENTIFIC PLOTTER, CURVE FITTER AND VIDICHART  
FOR USE WITH EPSON MX-70 AND EPSON MX-80 PRINTERS  
AND FOR THE PKASO\* PRINTER INTERFACE SERIES

Interactive Microware, Inc.  
P.O. Box 771  
State College, Pa 16801  
(814) 238-8294



The modifications for VIDICHART closely follow the changes described in the manual for use with the Silentype printer. Thus, make the same changes in lines 32, 974, 975, 978 and 979, and alter line 976 and 977 as follows:


976 IF C=17 THEN PRINT CHR\$(9)"15H" (or "G2" for the GRAPPLER).

977 IF C=20 THEN PRINT CHR\$(9)"80P"


Bear in mind that you must turn off the "cuted" mode (type CTRL U) before activating the printer by typing CTRL P, followed by the slot number. When the printer is on, type CTRL Q to print the screen image and type CTRL R to type report at the bottom of the screen echo so that characters are printed on both the screen and the printer.

### CURVE FITTING EXAMPLES


CUBICFORM




GEOMFORM



PEAKFORM




Used with the permission of Donald V. Tappan, 187 Rockwell Street, Norwich, CT 06360.




Norwich, CT 06360.

Used with the permission of Donald V. Tappan, 187 Rockwell Street,






APPLE COMPUTER, INC. MAKES NO WARRANTIES,  
EITHER EXPRESS OR IMPLIED, REGARDING THE ENCLOSED  
COMPUTER SOFTWARE PACKAGE, ITS MERCHANTABILITY  
OR ITS FITNESS FOR ANY PARTICULAR PURPOSE.



If you have purchased both the ADALAB hardware and the VIDICHAART software at the same time, the QUCIKI/O disk contains an updated version called VIDICHAARTD. This program is described in the note in the back of the ADALAB manual entitled "Using VIDICHAART software with the same curve fitter VIDICHAART and other

**Calibration Procedure Changes:** A zero offset potentiometer has been added for the D/A converter, as shown in the figure above. After calibrating the D/A and A/D converters as described in the ADALAB Hardware Manual, set the D/A output voltage to zero and adjust the D/A offset pot to give an A/D reading of zero volts. This may necessitate a slight readjustment of the D/A and A/D gain pots.



ADA LAB is shipped with jumpers set for installation in SLOT 2 and a range of +4 volts. The cables of the self-test adapter should be plugged into the sockets of the ADA LAB card as shown, with pin 1 at the upper right.

Attention: ADALAB users

Interactive Microwave, Inc.  
P.O. Box 771  
State College, Pa 16801  
(814) 238-8294





BASIC Programs." VIDICHARTAD requires an additional file called  
VISIOBJ, which is on the original disk for VIDICHART. Thus, to  
run VIDICHARTAD, You should first LOAD it from the QUCIKI/O disk and  
then SAVE it on a copy of the VIDICHART disk before RUNNING the pro-  
gram. The VIDICHARTAD update also requires the ADOBJ file from  
the QUCIKI/O disk. Therefore, you should also read ADOBJ from  
the QUCIKI/O disk (TYPE BLOAD ADOBJ, A\$320) and write it on the  
copy disk (TYPE BSAVE ADOBJ, A4320, L\$50).



**IMPORTANT:** This warranty does not cover damage resulting from accident, misuse, or abuse, lack of reasonable care, modifications, or repair of any defective unit without charge.

Interactive Microwave, Inc. (IMI) warrants each new ADALAB™ Interactive Microware, Inc. (IMI) warrant against defects in material or workmanship for a period of 90 days from the date of purchase and agrees to repair or replace any defective unit without charge.

Other than those done in accordance with instructions published by Interactive Microware, loss of parts or subjective testing the product to service or repair not performed by IMI or registered repair centers. This warranty applies only to the ADALAB Interface Board, chassis is expected to understantand the operational characteristics of this interface, as described in the documentation supplied by IMI, and to assess the suitability of ADALAB for his application.

This warranty is in lieu of all other warranties, expressed or implied, including warranties of merchantability and fitness for use. In no event will IMI be liable for incidental and consequential damages arising from the use of any ADALAB products or its products.

Inasmuch as IMI does not have sufficient information to evaluate the suitability of ADALAB for any particular application, the pur-chaser is expected to understand the operational characteristics of this interface, as described in the documentation supplied by IMI, and to assess the suitability of ADALAB for his application.

This warranty is in lieu of all other warranties, expressed or implied, including warranties of merchantability and fitness for use. In no event will IMI be liable for incidental and consequential damages arising from the use of any ADALAB products or its products.

This warranty is in lieu of all other warranties, expressed or implied, including warranties of merchantability and fitness for use. In no event will IMI be liable for incidental and consequential damages arising from the use of any ADALAB products or its products.

The purchaser of this product is hereby notified that the probability of failure of this device is not zero, and that this product is NOT RECOMMENDED for any use in dangerous or hazardous situations in which its failure has a chance of causing injury, damage or death.



A detailed description of the problem must be included. After the warranty period expires, IMI will repair or replace the card for a charge that will vary from \$25 to \$150, depending on the parts and labor required. In such cases, the product will be returned by UPS C.O.D. unless a company purchase order or payment in full has been received.

IMI Repair Service Department  
P.O. Box 771  
State College, PA 16801

This warranty extends only to the original purchaser. Proof of purchase is necessary for products returned for warranty service. To obtain service, return the product (postage paid) to:

Interactive Microwave, Inc.  
ADALAB Warranty Information  
Page 2

